

## **Vistra Moss Landing FAQs**

### **1. What happened?**

On Thursday, Jan. 16, we detected a fire at our Moss 300-MW energy storage facility at the Moss Landing Power Plant Site. Company personnel immediately responded, and the North Monterey County Fire District was quickly dispatched to the scene. They have been working around the clock to contain the fire, which remains ongoing. We're working closely with the Fire District to provide as much support as possible, and we're immensely grateful for their swift response to this event.

### **2. Is there any insight into the cause or suspected cause of the fire?**

We're focused on safely containing the fire and assisting the Fire District wherever we can. The cause of the fire has not yet been determined, but an investigation will begin once the fire is extinguished.

### **3. Should I be concerned about the air quality or my health?**

Vistra and public agencies, including the Environmental Protection Agency, are actively monitoring air quality. We are working cooperatively to ensure public health and safety, which is our top priority. So far, ongoing air monitoring has not detected anything hazardous. We will update this site with more information on monitoring results and any precautions that need to be taken as soon as we have the initial results.

### **4. What are you doing to support the local community impacted by this incident?**

Like many of our neighbors and friends, Moss Landing is our home, and we're committed to working closely with our community partners and local officials to determine how we can best help. We have and will continue to do everything we can to ensure the safety of our neighbors and do right by our community. In the coming days, we will update this site with more information on how we are supporting those who are impacted.

### **5. Have there been other fires at this facility in recent years?**

We have not experienced fires at any of our Vistra battery operations to date. In 2021 and 2022, we experienced unrelated overheating events at the Moss Landing Facility when water from the safety system caused electrical shorting on a portion of our batteries. You can find more information on the investigations and results from those incidents [here](#).